


Weathered irregular stone steps

Staircase Number: No.1



Original image




3D point-cloud scan

Narrow confined stairway with worn treads

Staircase Number: No.2



Original image




3D point-cloud scan

Block masonry steps with layered structure

Staircase Number: No.3



Original image




3D point-cloud scan

Regular granite stair steps with vegetation in joints

Staircase Number: No.4



Original image



3D point-cloud scan